Machinery (Fees) Determination 2017

Disallowable instrument DI2017-103

made under the

Machinery Act 1949, s 5 (Determination of fees)

1 Name of instrument

This instrument is the *Machinery (Fees) Determination 2017*.

2 Commencement

This instrument commences on 1 July 2017.

3 Revocation

This instrument revokes DI2016-67, the Machinery (Fees) Determination 2016.

4 Determination of fees

- (1) The fee payable for a matter stated in an item in the schedule, column 2 is the fee stated in the schedule, column 3 for that matter.
- (2) The fee for a matter stated in an item in the schedule, column 2 is payable by the person requesting the service.

5 Payment of fees

The fee payable for a matter stated in an item in the schedule, column 2 is payable to the Territory.

Rachel Stephen-Smith MLA Minister for Workplace Safety and Industrial Relations 31 May 2017

SCHEDULE - FEES AND CHARGES TO BE PAID

Column 1	Column 2	Column 3
Item	Matter in respect of which fee or charge is payable	Amount Payable
319	Inspection of Boiler – locomotive, traction engine or road roller boilers, having a heating surface not exceeding 7.50 square metres – fee per inspection Explanatory Note: Last Financial Year the fee was \$143.00.	\$148.00 (GST is not applicable)
320	Inspection of Boiler – locomotive, traction engine or road roller boilers, having a heating surface exceeding 7.50 square metres – fee per inspection <i>Explanatory Note: Last Financial Year the fee was \$204.00.</i>	\$212.00 (GST is not applicable)
321	Inspection of Boiler – other than locomotive, traction engine or road roller boilers having a heating surface, not exceeding 2 square metres – including economiser and superheater (if any) – fee per inspection* Explanatory Notes Last Financial Year the fee was \$52.00	\$54.00 (GST is not applicable)
322	Explanatory Note: Last Financial Year the fee was \$52.00. Inspection of Boiler – other than locomotive, traction engine or road roller boilers having a heating surface, exceeding 2 square metres but not exceeding 5 square metres – including economiser and superheater (if any) – fee per inspection Explanatory Note: Last Financial Year the fee was \$88.00.	\$91.00 (GST is not applicable)
323	Inspection of Boiler – other than locomotive, traction engine or road roller boilers having a heating surface, exceeding 5 square metres but not exceeding 15 square metres – including economiser and superheater (if any) – fee per inspection Explanatory Note: Last Financial Year the fee was \$143.00.	\$148.00 (GST is not applicable)
324	Inspection of Boiler – other than locomotive, traction engine or road roller boilers having a heating surface, exceeding 15 square metres but not exceeding 70 square metres – including economiser and superheater (if any) – fee per inspection <i>Explanatory Note: Last Financial Year the fee was \$204.00.</i>	\$212.00 (GST is not applicable)
325	Inspection of Boiler – other than locomotive, traction engine or road roller boilers having a heating surface, exceeding 70 square metres but not exceeding 200 square metres – including economiser and superheater (if any) – fee per inspection <i>Explanatory Note: Last Financial Year the fee was \$264.00</i> .	\$274.00 (GST is not applicable)
326	Inspection of Boiler – other than locomotive, traction engine or road roller boilers having a heating surface, exceeding 200 square metres but not exceeding 400 square metres – including economiser and superheater (if any) – fee per inspection <i>Explanatory Note: Last Financial Year the fee was \$278.00.</i>	\$289.00 (GST is not applicable)
327	Inspection of Boiler – other than locomotive, traction engine or road roller boilers having a heating surface, exceeding 400 square metres -including economiser and superheater (if any)	\$352.00 (GST is not applicable)
	plus per 100 metres or part thereof by which the heating surface exceeds 400 square metres Explanatory Note: Last Financial Year the fees were \$339.00 and \$9.00 respectively.	\$9.00 (GST is not applicable)
328	Inspection of Pressure Vessel – steam jacketed pan having internal diameter not exceeding 1 metre - fee per inspection* Explanatory Note: Last Financial Year the fee was \$45.00.	\$46.00 (GST is not applicable)
329	Inspection of Pressure Vessel – steam jacketed pan having internal diameter exceeding 1 metre – fee per inspection* Explanatory Note: Last Financial Year the fee was \$52.00.	\$54.00 (GST is not applicable)
330	Inspection of Pressure Vessel – other pressure vessels having an internal capacity not exceeding 150 litres – fee per inspection* Explanatory Note: Last Financial Year the fee was \$45.00.	\$46.00 (GST is not applicable)
331	Inspection of Pressure Vessel – other pressure vessels having an internal capacity exceeding 150 litres but not exceeding 1,500 litres – fee per inspection* Explanatory Note: Last Financial Year the fee was \$52.00.	\$54.00 (GST is not applicable)
332	Inspection of Pressure Vessel – other pressure vessels having an internal capacity exceeding 1,500 litres but not exceeding 3,000 litres – fee per inspection Explanatory Note: Last Financial Year the fee was \$88.00.	\$91.00 (GST is not applicable)
333	Inspection of Pressure Vessel – other pressure vessels having an internal capacity exceeding 3,000 litres – fee per inspection Explanatory Note: Last Financial Year the fee was \$127.00.	\$132.00 (GST is not applicable)

334

Notes:

- * Single Inspections: Where description of matter for which fee is payable in column 2 is marked * and on any one day in any one premises, an inspection is made of only one boiler or one pressure vessel, the fee to be charged for the inspection shall be 50 percent in excess of the fee otherwise payable.
- * Multiple Inspections: Where on any one day in any one premise, five or more boilers or five or more pressure vessels are inspected, the fee to be charged for the inspection shall be 30 percent less than the fees otherwise payable.