

# Radiation (Council Decision) Notice 2006 (No 8)

## Notifiable Instrument NI2006—413

made under the

*Radiation Act 1983, s 73 (1) Notification of decisions*

---

### 1 Name of instrument

This instrument is the Radiation (Council Decision) Notice 2006 (No 8).

### 2 Commencement

This instrument commences on the day after notification.

### 3 Notice of Decisions

The particulars of decisions of the Radiation Council are as stated in the schedule.

### 4 Right of Review

Any persons whose interests are adversely affected by these decisions may apply to the ACT Administrative Appeals Tribunal to have the decision reviewed. Write within 28 days explaining the details of the decision and the reasons for asking for a review. To lodge an application there is a fee. You may apply to have the fee waived on the grounds of hardship. No fee is payable if you are receiving legal assistance. The Tribunal is located on the 4<sup>th</sup> Floor, Canberra House, 40 Marcus Clarke Street, Canberra City, GPO Box 9955, Canberra ACT 2601, Telephone (02) 6243 4611, Facsimile (02) 6247 0962, Document Exchange DX 5727. The Tribunal is an independent body. The Tribunal can agree with, change or reject to the original decision, substitute its own decision or send the matter back to the decision maker for reconsideration in accordance with Tribunal recommendations.

### 5 Reasons

If you wish to obtain a statement of reasons to explain why the decision was made you should write within 28 days of this notice to the ACT Radiation Council, GPO Box 825, Canberra ACT 2601.

## **6 Access to documents**

You may apply for access to any documents relevant to this decision under the ACT *Freedom of Information Act 1989*. For more information contact the Freedom of Information Officer, ACT Health, telephone (02) 620 51340.

Professor Leslie Keith Fifield  
Deputy Chairperson Radiation Council  
8 November 2006

## SCHEDULE

### **GRANTING of a LICENCE (s 73(1)(c))**

#### *With conditions*

Licensee	David Keith Oliver
Address	ACT Wide
Authorised Activities:	use, irradiating apparatus
Conditions	Use of irradiating apparatus is limited to servicing, maintenance and installation. Council must be provided on a quarterly basis with a list of all servicing, maintenance and installations conducted by the licensee within the ACT. Nil returns are also required.
Licensee	Eugene Wong
Address	ACT Wide
Authorised Activities:	use, irradiating apparatus
Conditions	Testing of x-ray apparatus within the ACT. Use of irradiating apparatus is limited to testing. Council must be provided on a quarterly basis with a list of all testing conducted by the licensee within the ACT. Nil returns are also required.

### **REGISTRATION of an IRRADIATING APPARATUS (s 73(1)(e))**

Owner	Dr Carmelo Bonanno
Description	Sirona D3352 / 5884999 S/n: 03282. Tube 1117340V1010 S/n: 112202 90 kVp, 12mA.
Location	Suite 1 Gadai Chambers 48 Corinna Street WODEN ACT 2606
Conditions	Diagnostic dental radiography.
Owner	Dr Samuel L Whittle
Description	Sirona Orthophos XG Plus S/n: 41389. Tube Housing Sirona 5884999D3352. S/n: 04442. Tube Insert Siemens SR90/FN 15 S/n: 7111218. 90kVp, mA12.
Location	X-ray/Utility Room 1st Floor, Gadai Chambers 48 Corinna Street WODEN ACT 2606
Conditions	Diagnostic dental radiography.
Owner	Preventive Dental Care Pty Ltd
Description	Trophy CCX. S/N: C2830016. X-Ray tube housing Trophy IRIX70. S/N:XAMG0624. 70kVp, 8mA
Location	Room 3 Suite 6 Deakin Court Hopetoun Circuit DEAKIN ACT 2600
Conditions	Diagnostic dental radiography.

Owner	ACT X-Ray Services
Description	Toshiba, Aquilion 16. S/n: 6398-6-T/H63968. Tube Housing - Toshiba CGGT-018A. S/n: 1AD0683237.. 135kVp, 400mA.
Location	CT Room Ground Floor John James Clinical Services Building 175 Strickland Crescent DEAKIN
Conditions	Diagnostic Radiography
Owner	John Aspley-Davis
Description	Eureka Vet APR. S/n: 6C019. Tube housing Toshiba, E7242X. S/n: 6B019. 150kVp, 400mA.
Location	Radiography Room Kippax Veterinary Hospital 82 Hardwick Crescent HOLT
Conditions	Veterinary radiography.
Owner	Medical Imaging TCH
Description	Siemens Axiom Artis MP S/n:2756. Acc No:21560. X-ray tube housing: Siemens 05662106H S/n: 3123H. 130 kVp, 4 mA.
Location	Fixed unit. Capable of continuous exposure. Room 3, 2nd Floor Building 12 Medical Imaging Department The Canberra Hospital GARRAN ACT
Conditions	Diagnostic Radiography.
Owner	ACT X-ray Services Pty Ltd
Description	Toshiba Aquillion S/n: 2AA03683607. X-ray tube housing: Toshiba S/n: 1AD0683230. Tube insert: Toshiba TSX-101A. S/n: GCB0682677. 130kVp, 400mA.
Location	CT Room Calvary Clinic Mary Potter Circuit BRUCE
Conditions	Diagnostic radiography
Owner	Ravindraraj DURASINGAM
Description	Gendex x-ray machine Model 765DC with Gendex GX 70/10DC tube housing, Serial Nos 15-1719969DP, 10-1719560DP 65kVp, 7mA
Location	Dental Surgery Kambah Medical Centre Jenke Circuit KAMBAH ACT 2902
Conditions	Diagnostic dental radiography.
Owner	Dr Carmelo Bonanno
Description	Sirona 4681263 (D3302) Sn. 44894. Tube 3343741 (V 1034) Sn. 507902. 60 kVp, 7 mA.
Location	Suite 1 Gadai Chambers 48 Corinna Street WODEN ACT 2606
Conditions	Diagnostic dental radiography.

Owner	Preventive Dental Care P/L
Description	Soredex Minray S/N:i601016. X-ray tube housing: Soredex INTH 1 S/N:2310. Tube D-0711S S/N:4972 70kVp, 7mA.
Location	Room 2 Suite 6 Deakin Court Hopetoun Circuit DEAKIN ACT 2600
Conditions	Diagnostic dental radiography.
Owner	ACT X-Ray Services
Description	Philips Xpert FD20 Allura S/n: 55343. Tube Housing Philips 989000085102, S/n: 14212M104443. 125 kVp, 1000 mA.
Location	Angiography & Daycare Suite Canberra Imaging Group John James Memorial Hospital Strickland Crescent DEAKIN ACT
Conditions	Use of irradiating apparatus for diagnostic medical purposes.
Owner	Preventive Dental Care P/L
Description	Soredex Minray S/N:i600964. Xray tube housing: Soredex INTH1. S/N:977. Tube S/N: D-0711S 70kVp, mA7.
Location	Room 1, Suite 6 Deakin Court Hopetoun Circuit DEAKIN ACT 2600
Conditions	Diagnostic dental radiography
Owner	Preventive Dental Care Pty Ltd
Description	SIRONA XG 3 OPG S/N: 100126 X-ray tube housing. SIRONA 60-90kVp and 3-16 mA.
Location	OPG Room Suite 6 Deakin Court Hopetoun Circuit DEAKIN ACT 2600
Conditions	Diagnostic dental radiography.
Owner	Linh Nguyen
Description	Soredex SL - 4/PT-11 Cranex Excel D. K612638 DM. Tube: Soredex PT-11. S/n: 1303899 81kVp, 6mA
Location	Surgey 3 Kambah Professional Centre 51 Jenke Circuit KAMBAH ACT
Conditions	Diagnostic dental radiography.
Owner	ACT X-ray Services Pty Ltd
Description	Planmeca Proline XC with X-ray tube housing Planmeca EC/CC Proline XC. S/nos: XC 427181, 6BO3002(tube), RTH 061708. 80 kVp, 12mA.
Location	OPG Room Valley Diagnostic Centre Grattan Court ERINDALE
Conditions	Diagnostic radiograph

**APPROVAL for an ALTERATION or MODIFICATION of a REGISTERED  
IRRADIATING APPARATUS (s 73(1)(f))**

*Include "Reason"*

Reason	Major component replacement.
Owner	Graeme Flett
Description	Sirona Heliodont DS S/n: 12881. x-ray tube housing Sirona 4681263 D3302 S/n:28697 60kVp, 7mA.
Location	Room 2 Unit 3 Medical Centre Blamey Place CAMPBELL
Conditions	Diagnostic dental radiography
Reason	Major component replacement.
Reason	Alteration in the location of the machine.
Owner	ACT X-ray Services Pty Ltd
Description	Toshiba Aquillion CT scanner S/n: A0592223 x-ray tube housing: Toshiba CGGT-041A. S/n: A0592004. 130 kVp, 400mA.
Location	CT Room Canberra Imaging Group Lakeview Square, 21 Belconnen Way BELCONNEN ACT 2617
Conditions	Diagnostic radiography.

**APPROVAL for an ALTERATION in the LOCATION, INSTALLATION or SHIELDING of  
a REGISTERED IRRADIATING APPARATUS (s 73(1)(g))**

Reason	Alteration in the location of the machine.
Owner	National Capital Diagnostic Imaging
Description	Diagnostic Fluoroscopy II / Radiography machine Philips Optimus duo-diagnost with ROT350 tube S/Nos 89000427, 6397150. 125kVp, 400mA
Location	Screening Room NCDI Corinna Chambers Corinna St, WODEN
Conditions	Diagnostic radiography.
Reason	Alteration in the location of the machine.
Owner	ACT X-Ray Services Pty Ltd
Description	Diagnostic CT scanner x-ray machine Toshiba CXXG-008A/1A with Varian CXB-750C tube S/Nos AO562194, 14490-OS 135kVp 400mA
Location	CT Room Valley Medical Centre Grattan Court ERINDALE ACT
Conditions	Diagnostic radiography.

Reason	Alteration in the location of the machine.
Owner	ACT X-ray Services Pty Ltd
Description	Norland Excell 433a025 bone mineral densitometer. S/n: 8112 x-ray tube housing Toshiba 391A68, S/n:3251 100kVp, 1.3mA
Location	BMD Room 1st Floor Clinical Services Building John James Memorial Hospital DEAKIN ACT
Conditions	Bone density analysis.