

Radiation (Radiation Council Decisions) Notice 2004 (No 5)

Notifiable instrument NI2004-285

made under the

Radiation Act 1983, s 73 (1) – Notification of decisions

I notify the following particulars of decisions of the Radiation Council as stated in the schedule.

Code of Practice under s25B(1) of the Administrative Appeals Tribunal Act 1989

Review by the ACT Administrative Appeals Tribunal – Any persons whose interests are adversely affected by these decisions may apply to the Tribunal to have the decision reviewed.

Reasons – If you wish to obtain a statement of reasons to explain why the decision was made you should write within 28 days of this notice to the

ACT Radiation Council, GPO Box 825, Canberra ACT 2601

Location of the ACT Administrative Appeals Tribunal – The Tribunal is located on the 4th Floor, Canberra House, 40 Marcus Clarke Street, Canberra City.

Postal Address : GPO Box 9955, Canberra 2601. Telephone : 6243 4611. Facsimile : 6247 0962. Document Exchange : DX 5727

Powers of the ACT Administrative Appeals Tribunal – The Tribunal is an independent body. The Tribunal can agree with, change or reject to the original decision, substitute its own decision or send the matter back to the decision maker for reconsideration in accordance with Tribunal recommendations.

How to apply to the ACT Administrative Appeals Tribunal – Simply write within 28 days explaining the details to the decision and the reasons for asking for a review.

Cost – To lodge an application there is a fee. You may apply to have the fee waived on the grounds of hardship. No fee is payable if you are receiving legal assistance.

Access to documents – You may apply for access to any documents relevant to this decision under the ACT *Freedom of Information Act 1989*. For more information contact the Freedom of Information Officer, Department of Health and Community Care, on phone 620 51340.

Anthony Agostino
Chairperson
Radiation Council
11 August 2004

SCHEDULE

REGISTRATION of an IRRADIATING APPARATUS (s 73(1)(e))

Owner	Dr Spiro Pazios	
Description	Dental x-ray machine (OPG & Ceph). Instrumentarium System no 81816	Generator Sn
	14148 & Toshiba Tube Sn 14148. 85kVp 20 mA	
Location	X-ray room, Suites 5 & 6, 1st Floor Manuka Plaza Professional Suites Flinders Way Manuka	
Conditions	Diagnostic dental examinations.	
Owner	Dr Anita Shroot	
Description	Belmont 096-C dental x-ray unit with Belmont D-088 tube. S/Nos C10350, T-91954. 70kVp, 10mA	
Location	Room 1 Dental Surgeries Dickson Park Professional Centre Cnr Cowper & Antill Streets Dickson	
Conditions	Diagnostic dental examinations.	
Owner	Dr David Chan	
Description	Trophy Elitys dental x-ray machine with Trophy TRX-708 tube S/Nos RHX1160, 03290143, RIXB089, 328039. 70kVp, 7mA	
Location	Room 1, Suite 3, Level 2, Lakeview House Cowlshaw Street Tuggeranong	
Conditions	Diagnostic dental examinations.	
Owner	Dr David Chan	
Description	Trophy Elitys dental x-ray machine with Trophy TRX-708 tube S/Nos RHX1161, 03290146, RIXB104, 328110. 70kVp, 7mA	
Location	Room 2, Suite 3, Level 2, Lakeview House Cowlshaw Street Tuggeranong	
Conditions	Diagnostic dental examinations.	
Owner	ACT Community Care, Dental Services	
Description	Gendex-765DC dental x-ray machine with Gendex-GX70-10-DC tube. S/Nos 15646710DP, 11514, 10-1645448DP. 65kVp, 7.5 mA	
Location	Room 6 Belconnen Health Centre Benjamin Way Belconnen	
Conditions	Diagnostic dental examinations.	

Owner	Dr Anthony Dawson
Description	Gendex 765DC dental x-ray machine with Gendex GX70-10DC tube. S/No 15-168438DP, 10-1634710DP. 65kVp, 7mA
Location	Room 1, Suite 9 Lidia Perin Medical Centre Napier Close Deakin
Conditions	Diagnostic dental examinations.
Owner	Dr Sherry Guo & Dr Andrew Chang
Description	Sirona Heliodont DS dental x-ray machine S/no 24014, 26003 with Heliodont DS tube. S/Nos 32198, 31229. 60kVp 7mA
Location	Room 1 Dickson Dental TLC Woolley Street, Dickson
Conditions	Diagnostic dental examinations.
Owner	Dr Van Trinh
Description	Trophy Elitys dental x-ray machine with Trophy TRX-708 tube S/Nos SDX1413, SDXB382/408272. 60kVp, 7mA
Location	Room 1, Suite 1.6 (First floor) Gungahlin Marketplace Dental Centre 33 Hibberson Street Gungahlin
Conditions	Diagnostic dental examinations.
Owner	Yohaku Pty Ltd & Jessam Properties Pty Ltd
Description	Gendex 765DC dental x-ray machine with Gendex GX-70-10DC tube. S/Nos 15-1047867, 12512, 10-1658338DP. 65kVp 7.5 mA
Location	Room 2 Suite 3, 1st Floor Centre Cinema Building Bunda Street Canberra
Conditions	Diagnostic dental examinations.
Owner	Dr Vincent Ngoctrai Tran
Description	Trophy Elytis TR-1 dental x-ray machine with Trophy TRX-708 tube. s/nos 2K24J0036, 021124. 70kVp, 4mA
Location	Room 1, Gungahlin Dental Surgery 37 Anthony Rolfe Ave Gungahlin
Conditions	Diagnostic dental examinations.

Owner	Canberra Hospital, Medical Imaging
Description	Diagnostic mobile x-ray machine GE model AMX4 Plus with model 2185226 tube. S/Nos 300060-174003, 2781BC6. 125kVp 320 mAs
Location	Mobile radiography unit Medical Imaging Department Canberra Hospital Garran
Conditions	Diagnostic radiography.

GRANTING of a LICENCE (s 73(1)(c))

Licensee	Dr George Koperski
Address	ACT Radiation Safety Section premises and facilities. 25 Mulley Street HOLDER ACT 2611
Authorised Activities:	Purchase, own or have in possession, use, cause or permit to use, unsealed radioactive materials, irradiating apparatus.
Conditions	As Manager - Radiation Safety Section, ACT Health: Supervision of the Section and its activities, including performance of duties as an inspector under the Radiation Act. Use excludes irradiating apparatus containing equipment (namely medical X-ray machines).
Licensee	Dr Ahmad Javaid
Address	Building 12, Level 2, Department of Nuclear Medicine The Canberra Hospital Yamba Drive, GARRAN ACT 2605
Authorised Activities:	Purchase, own or have in possession, use, cause or permit to use, unsealed radioactive materials.
Conditions	Nuclear medicine procedures involving diagnostic/therapeutic medical uses of: * Tc-99m, Ga-67, I-131, P-32, C-14, Cr-51, Tl-201, Sr-89, I-125, Y-90, I-123, Se-75, In-111, Sm-153, Cs-137, Co-57, Mo-99.
Licensee	Jacqueline Kearslake
Address	35 Brigalow Street O'CONNOR ACT 2602
Authorised Activities:	Use, cause or permit to use, irradiating apparatus.
Conditions	Diagnostic dental examinations.

VARIATION of CONDITION SPECIFIED in a LICENCE (s 73(1)(d))

Reason	Additional Conditions added: Purchase, own or have in possession.
Licensee	Dr Van Trinh
Address	20 Ferguson Circuit Ngunnawal ACT 2913
Authorised Activities:	Purchase, own or have in possession, use, cause or permit to use, irradiating apparatus
Conditions	Diagnostic dental radiography.

**APPROVAL for an ALTERATION or MODIFICATION of a REGISTERED
IRRADIATING APPARATUS (s 73(1)(f))**

Reason	Replacement of major components.
Owner	National Capital Diagnostic Imaging
Description	Diagnostic x-ray unit Philips Medio 50 CP with Philips tube. S/Nos 932072, B1499, 927085.
Location	Fracture Clinic Corinna Chambers Corinna Street Woden
Conditions	Diagnostic radiology.

Reason	Replacement of major components.
Owner	National Capital Diagnostic Imaging
Description	Siemens Somatom CT Helical Scanner model ARPHGEL 2047 Spiral, System No 13085 ROTANK MCT-141 tube, s/no 01068, 130 kVp, 105 mA
Location	CT Room, National Capital Diagnostic Imaging Corinna Chambers Corinna Street Woden
Conditions	Diagnostic radiography.

Reason	Replacement of major components.
Owner	Dr David G Griffiths
Description	Philips dental x-ray unit models: Densomat/Oralix 65 S. S/Nos 8623927, 4050402. 65kVp, 7.5mA
Location	Room 2 Suite 6, Ethos House Ainslie Avenue Canberra City
Conditions	Diagnostic dental examinations.

**APPROVAL for an ALTERATION in the LOCATION, INSTALLATION or SHIELDING of a REGISTERED
IRRADIATING APPARATUS (s 73(1)(g))**

Reason	Change of business name, and change of location
Owner	Yohaku Pty Ltd & Jessam Properties Pty Ltd
Description	Gendex 765DC dental x-ray machine, S/Nos 11-149050519DP & model GX-70-10DC tube, S/Nos 1211, 10-1494865DP, 65kVp 7.5mAs
Location	Room 1, Suite 3, 1st Floor Centre Cinema Building Bunda Street Canberra
Conditions	Diagnostic dental examinations.

Reason	Change of location
Owner	Christopher Bourke
Description	Sirona Heliodont DS dental x-ray machine, with Siemens SR 60/70/7L tube, S/Nos 11130/12239, 17865/297360. 60kVp 7mA
Location	Room 2, Level 4 28 University Avenue Canberra City
Conditions	Diagnostic dental examinations.

Reason	Change of location
Owner	Dr Vincent Tran
Description	Dental X-Ray machine: Belmont Searcher DX068 with Toshiba D-081B Tube, s/nos N08026 / 86087. 65kVp, 8mA
Location	Room 2, Gungahlin Dental Surgery 37 Anthony Rolfe Avenue Gungahlin
Conditions	Diagnostic dental examinations

GRANTING of a DISPOSAL PERMIT (s 73(1)(j))

Permit Holder	Dr Ahmad Javaid
Licensed Premises	Department of Nuclear Medicine Building 12, Level 2 Canberra Hospital Yamba Drive Garrahan

Radionuclide contained in the material for disposal	Physical and chemical form of the material	Annual quantity of material for which approval is granted	Disposal method approved
Carbon-14	Scintillation fluid	1.00 MBq	Incineration-Mitchell
Iodine-131	Organified urine	300.00 GBq	Dedicated sewer
		(Labelled sewer line - Building 3)	